## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>V</b>			
Environment				
Floor surface	•			
Signs	<b>V</b>			
Gates	<b>V</b>			
Fences	<b>V</b>			
Benches	<b>V</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	<b>~</b>			
Multi Play	<b>V</b>			
Roundabout	•			
Spring See-Saw	<b>V</b>			
2Bay Swing	<b>V</b>			

Date	24/07/2025	Time Complete	<b>d</b> 1115			
Weath	er Conditions Sunny					
Additional Observations						
Signatu	reD Matthews	Name				
Signatu	re	Name				

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	•			
Defibrillator – solid icons displayed	•			
CCTV Cameras - free from cobwebs	•			
Sewerage Plant (Listen and warning light)	<b>V</b>			
Container	•			
Outfield	•	Youth cricket being played – observed from edge of field		
Site Boundaries, Fences and Hedges	•	Youth cricket being played – observed from edge of field		
Bins				

Weather	Conditions	Sunny
---------	------------	-------

## **Additional Observations**

Signature	D Matthews	Name	
J			
Signature		Name	
Date	24/07/2025		