AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	1	Equipment in use – visual inspection		
Environment	Ť			
Floor surface				
Signs	/			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile		Equipment in use		
Multi Play	V			
Roundabout	V			
Spring See-Saw	V			
2Bay Swing	V			

Date	26/11/2025	Time Complete	ed1430				
Weather Conditions cool and sunny							
Additional Observations							
Signatu	reB Nanson	Name					
Signatu	re	Name					

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	V			
Pavilion Inc fire extinguishers	V			
Defibrillator – solid icons displayed	V			
CCTV Cameras - free from cobwebs	V			
Sewerage Plant (Listen and warning light)	~			
Container	V			
Outfield	•			
Site Boundaries, Fences and Hedges	V			
Bins	•			

Additional Observations

Signatur	e	B Nanson	Name	
Ü				
Signatur	e		Name	
Ü				
Date	26/11	/2025		