AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface	•			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	V			
Roundabout	•			
Spring See-Saw	V			
2Bay Swing	V			

Date	14/0//2025	Time Complete	d1015		
Weather Conditions Sunshine					
Additio	nal Observations				
Signatu	reB Nanson	Name			
Signatu	re	Name			

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	V			
Pavilion Inc fire extinguishers	V			
Defibrillator – solid icons displayed	V			
CCTV Cameras - free from cobwebs	V			
Sewerage Plant (Listen and warning light)	~			
Container	V			
Outfield	•			
Site Boundaries, Fences and Hedges	V			
Bins	•			

vveatilei collattions sunsimile	Weather	Conditions	Sunshine
---------------------------------	---------	------------	----------

Additional Observations

Signature	B Nanson	Name	
-			
Signature		Name	
Date14/07	7/2025		