## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	<b>1</b>			
Environment				
Floor surface				
Signs	<b>/</b>			
Gates	<b>/</b>			
Fences	<b>V</b>			
Benches	<b>V</b>			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile		Playground in use so not closely inspected.		
Multi Play				
Roundabout				
Spring See-Saw				
2Bay Swing				

Date	24/10/2025	Time Completed	<b>d</b> 1115					
Weather Conditions cool and sunny								
Additional Observations								
Signatu	reD Matthews	S Name						
Sianatu	rο	Name						

## AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	•			
Pavilion Inc fire extinguishers	<b>V</b>			
Defibrillator – solid icons displayed	•			
CCTV Cameras - free from cobwebs	•			
Sewerage Plant (Listen and warning light)	•			
Container	<b>V</b>			
Outfield	<b>V</b>			
Site Boundaries, Fences and Hedges	<b>V</b>			
Bins	•			

## **Additional Observations**

Signature	D Matthews	Name	
J			
Signature		Name	
Date24/10	)/2025		