AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	✓			
Environment	•			
Floor surface	\checkmark			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	✓			
Multi Play	√			
Roundabout	√			
Spring See-Saw	√			
2Bay Swing	√			

Date 31st October 2025 Time Completed 11:05pm

Weather Conditions Light rain, warm

Additional Observations

Signature CJ Ling Name CJ Ling

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion Inc fire extinguishers	✓			
Defibrillator – solid icons displayed	✓			
Sewerage Plant (Listen and warning light)	✓			
Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Additional Observations								
Signature	C J Ling	Name CJLing						

Light rain, warm

Date 31st October 2025

Weather Conditions