AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Auxiliary			Risk	Time Scale
Items	OK?	Issues	L/M/H	
General	V			
Environment				
Floor surface	•			
Signs	V			
Gates	V			
Fences	V			
Benches	V			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
Turnstile	~			
Multi Play	V			
Roundabout	•			
Spring See-Saw	V			
2Bay Swing	V			

Date	23/09/2025	Time Complete	d 0945				
Weather Conditions cool and sunny							
Additional Observations							
Signatu	reB Nanson	Name					
Signatu	re	Name					

AMPFIELD RECREATION GROUND - Playground & Pavilion Inspection

Area	OK ?	Issues	Risk L/M/H	Time Scale
Entrances	V			
Pavilion Inc fire extinguishers	V			
Defibrillator – solid icons displayed	V			
CCTV Cameras - free from cobwebs	V			
Sewerage Plant (Listen and warning light)	~			
Container	V			
Outfield	•			
Site Boundaries, Fences and Hedges	V			
Bins	•			

Additional Observations

Signature	B Nanson	Name	
•			
Signature		Name	
	. /		
Date 23/09)/2025		